Work Order Wednesday, April	r ID 57508 07, 2010 3:41:55 PM	,	al								Page 1
Revision ID: Item Name: B Start Date: 4 Required Date: 4	D4010-041 Bearpaw Assembly 77/2010 Start Qty: 1.00 /14/2010 Req'd Qty: 1.00 Return 2010 / RA110008 / NCR	50		Accept	Cust Item I			s s	Setup Sta	1100111011	
	Process Plan: QC:	Date:	1004-07	Tooling: SPC (Y/N):	Date:		Run Start Stop				
Sequence ID/ Work Center ID	Operation Description			Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revision Nbr						Cour	Qij	Qtj	Number	Stamp
D4010-041	С						- 1				
100 QC	Memo			0.00			Ī	1			1004
Quality Control	Original B	53815. See I is tagged for	NCR10-020 for m r referance.	ore details. Part is scra	ap, but not yet		1				
10	QC21- Final Inspection	ı - Work Ord	ler Release	0.00						101	ou les de
QC Quality Control	Memo			0.00						101	111-1
passing Collifor										Y	nr u

	griff (4)
والمراجع والمتحال وال	and the state of t